



For Immediate Release
HINGHAM POLICE
DEPARTMENT

Contact P.I.O. Lt. Steven Dearth
dearths@hpd.org 781-804-2205
hpd.org

December 28, 2023

Driver Ejected During Roll Over Crash

Hingham, MA - A driver was injured after being ejected during a roll over car crash on George Washington Blvd Wednesday night.

On Wednesday December 27, 2023 at approximately 8:21pm Officers responded to a crash on George Washington Blvd. in front of the Hingham District Courthouse. Officers found a vehicle, a 2010 Hyundai Sonata, on its roof with the driver lying on the road. An investigation showed the Hyundai was traveling north on George Washington Blvd. at a high rate of speed when it abruptly swerved over the center line into the oncoming lanes. It continued across the two oncoming southbound lanes, over the sidewalk, off the road into a large rock and trees. It then rolled over landing back in the southbound lanes. The driver was alone and no other cars were involved.

The driver, a 17 year old female, was transported to South Shore Hospital with non-life threatening injuries. The driver was issued citations for 1) Negligent Operation 2) Marked Lanes Violation 3) Speeding 4) Seat Belt Violation. The driver was not wearing her seat belt. The driver's seat belt had been in the latched position behind the driver's seat. This is sometimes done to avoid the seat belt warning system when the seat belt is not used.

###